



SysQue

SOFTWARE

This document provides basic information about new features and modifications in the release of the Trimble® SysQue® software. More detailed information can be found in the online help system.

Introduction

These release notes describe the features and enhancements that are new for the major installer release dated 2018-04-25. For additional assistance, please email sysquesupport@trimble.com or call 1-800-234-3758.

Upgrade procedure

To download the major release, log into the SysQue support forum at <https://sysquesupport.zendesk.com>. Browse to General Information / Updates, SysQue Software Downloads and select the installer required for your Revit version.

To update previously installed SysQue software, select Update. For new installations, select Full installer for the year of Revit you have installed.

For additional instructions see the document SysQue Full Installation Instructions also available on the forum under SysQue Software Downloads.

Compatibility

Autodesk software

This release of SysQue is compatible with the current releases of Autodesk® Revit® versions 2016, 2017, 2018.

Windows

SysQue is compatible with Microsoft® Windows® versions 7, 8, and 10.

Backward compatibility

Digital models produced in Revit cannot be saved to or opened in previous versions.

Version: 5.3

Date: April 2018

New Features, Enhancements, and Updates

This section includes a brief introduction to new features. For more detailed instructions log into the SysQue support forum at <https://sysquesupport.zendesk.com/hc/en-us> and browse to the appropriate category.

Duct

- Additional improvements for Duct have been provided in this release to address reported issues for full cut length, duct numbering to analyze more parameters for differences, duct crashing with gaming mice, double wall duct, and updated taps.

Electrical

- Improved the processing speed for Conduit processing.
- Added gaskets between straights and fittings on Wireway.
- Fixed the mismatch error when importing an Excel file into Specification Settings.

Pipe

- Additional improvements for Pipe have been provided in this release to address reported issues with direct connect valves, valve adapter connectivity, and new connectivity for “Mechanical Joint Valves”.

PAC

- Additional improvements for PAC have been provided in this release to address reported issues for fittings, transitions, taps, offsets, material, and exporting to FabShop, Camduct, Practicam, and Vicon.
- Exports to FabShop now use default specifications.

Supports

- Fixed the issue with placing hangers on Ladder tray with clearances.
- Added the “Project Data” feature.

BOM

- Speed enhancement for creating the Bill of Materials.

Known Issues

General

If you are downloading/backfilling families for the first time, you may need to run “SetConnectorInfo” in a blank non-SysQue Revit model for SysQue to set the correct Connector End types. It’s recommended that you do this before you start using the Electrical and Pipe modules.

Spooling

There is a change that was made to the Revit 2018 API that has caused an issue with creation of spool drawings that use non-3D views. The other views are not being properly “Cropped”. As a work-around you can create only 3D views and orient them as if they were Plan or Section views.

Legal Notices

Trimble Inc.

116 Inverness Drive East, Suite 210

Englewood, Colorado 80112

800-234-3758

Copyrights and Trademarks

©2017, Trimble Inc. All Rights reserved. Trimble, the Globe & Triangle logo, and SysQue, are trademarks of Trimble Inc., registered in the United States and in other countries. Microsoft, and Windows are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries. Revit is a registered trademark or trademark of Autodesk, Inc. All other trademarks are the property of their respective owners.

Release Notice

This is the April 2018 release (V5.3) of the Release Notes. It applies to version 2018-04-25 of the SysQue software.

It pertains to the release noted elsewhere in this document. The topics within this document are subject to change without notice. Screenshots included may not be exactly as in the software application.