

RELEASE NOTES

Trimble® MEP Software, 2.3.0

This document contains late-breaking product information, updates, and troubleshooting tips not covered in the Trimble® MEP documentation.

- [Introduction](#)
- [New Features](#)
- [Removed Features](#)
- [Legal Notices](#)

Introduction

These Release Notes describe the enhancements that are new in version 2.3.0 of the MEP software.

New Features

File size improvements

Trimble MEP now offers improved performance when using large (5 MB - 10 MB) .mep job files. A warning appears indicating that performance may be adversely affected when a Trimble MEP job file of 10 MB or greater is opened.

Language support

Trimble MEP 2.3.0 is available in:

- English
- Chinese (Simplified)

- Dutch
- French
- German
- Japanese
- Korean
- Russian

A separate installer is provided for each language.

Removed Features

The following features that do not pertain to the mechanical, electrical, and plumbing trades have been removed from the *Blueprint* menu:

- **Two Tape Intersection** – You can no longer create points by entering distances from two known points.
- **Point Patterns** – You can no longer create points using a Point Pattern file.
- **Closure Check** – You can no longer perform a closure check on a Blueprint plan.

Legal Notices

Trimble Navigation Limited
Building Construction Division
10355 Westmoor
Westminster, CO 80021
USA

www.trimble.com

Copyright and Trademarks

© 2012, Trimble Navigation Limited. All rights reserved.

Trimble, and the Globe & Triangle logo are trademarks of Trimble Navigation Limited, registered in the United States and in other countries.

All other trademarks are the property of their respective owners.

Release Notice

This is the April 2012 release (Revision A) of the *Trimble MEP Software Release Notes*. It applies to version 2.3.0 of the MEP software.